

**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** FARNOW, INC.

Company/Organization: Farnow, Inc.

Address: 77 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins

Address: 89 Jacobus Avenue

County: Hudson Municipality: Kearny Town Lot: 13 Block: 289

Easting (X): 599340 Northing (Y): 694066  
Coordinate System: NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 2, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_

**Local ID:** MW-4

Reason for Decommissioning: No longer in use

Finished Well Depth (ft.): 18

Was a New Well Drilled? N

Formation Type: Unconsolidated

New Well Permit Number: \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material        | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|-----------------|--|
| Borehole |                       |                          |                      |                 |  |
| Casing   | 0                     | 2                        | 4                    | Stainless Steel |  |
| Screen   | 2                     | 17                       | 4                    |                 |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                        | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 17                       | 4                       | 0                      | 0                | 120                | 7            |
| Sand/Gravel |                       |                          |                         |                        |                  |                    |              |

**ADDITIONAL INFORMATION**

Obstructions: No

Authorization Official: \_\_\_\_\_

Obstruction Type: \_\_\_\_\_

Authorization Number: \_\_\_\_\_

Alternative Decomm. Method? No

Authorization Date: \_\_\_\_\_

Method Used \_\_\_\_\_

ATTACHMENTS: \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206  
Company: Netcong (Morris), NJ 07857

**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** FARNOW, INC.

Company/Organization: Farnow, Inc.

Address: 77 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins

Address: 89 Jacobus Avenue

County: Hudson Municipality: Kearny Town Lot: 13 Block: 289

Easting (X): 599472 Northing (Y): 693957  
Coordinate System: NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 2, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_ **Local ID:** MW-5

Reason for Decommissioning: No longer in use

Finished Well Depth (ft.): 20 Was a New Well Drilled? N

Formation Type: Unconsolidated New Well Permit Number: \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material        | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|-----------------|--|
| Borehole |                       |                          |                      |                 |  |
| Casing   | 0                     | 2                        | 4                    | Stainless Steel |  |
| Screen   | 2                     | 17                       | 4                    |                 |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 17                       | 4                       | 0                       | 0                | 120                | 7            |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

**ADDITIONAL INFORMATION**

Obstructions: No Authorization Official: \_\_\_\_\_

Obstruction Type: \_\_\_\_\_ Authorization Number: \_\_\_\_\_

Alternative Decomm. Method? No Authorization Date: \_\_\_\_\_

Method Used \_\_\_\_\_

ATTACHMENTS: \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206  
Company: Netcong (Morris), NJ 07857

**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** FARNOW, INC.

Company/Organization: Farnow, Inc.

Address: 77 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins

Address: 89 Jacobus Avenue

County: Hudson Municipality: Kearny Town Lot: 13 Block: 289

Easting (X): 599679 Northing (Y): 694219  
Coordinate System: NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 2, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_

**Local ID:** MW-6

Reason for Decommissioning: No longer in use

Finished Well Depth (ft.): 20

Was a New Well Drilled? N

Formation Type: Unconsolidated

New Well Permit Number: \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material        | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|-----------------|--|
| Borehole |                       |                          |                      |                 |  |
| Casing   | 0                     | 2                        | 4                    | Stainless Steel |  |
| Screen   | 2                     | 12                       | 4                    |                 |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 12                       | 4                       | 0                       | 0                | 94                 | 5.25         |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

**ADDITIONAL INFORMATION**

Obstructions: No

Authorization Official: \_\_\_\_\_

Obstruction Type: \_\_\_\_\_

Authorization Number: \_\_\_\_\_

Alternative Decomm. Method? No

Authorization Date: \_\_\_\_\_

Method Used \_\_\_\_\_

ATTACHMENTS: \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206  
Company: Netcong (Morris), NJ 07857



## WELL DECOMMISSIONING REPORT

**PROPERTY OWNER:** FARNOW, INC.

Company/Organization: Farnow, Inc.

Address: 77 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins

Address: 89 Jacobus Avenue

County: Hudson Municipality: Kearny Town Lot: 13 Block: 289

Easting (X): 598476 Northing (Y): 693940  
Coordinate System: NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 2, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_

**Local ID:** MW-10 R

Reason for Decommissioning: No longer in use

Finished Well Depth (ft.): 12

Was a New Well Drilled? N

Formation Type: Unconsolidated

New Well Permit Number: \_\_\_\_\_

### **WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material        | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|-----------------|--|
| Borehole |                       |                          |                      |                 |  |
| Casing   | 0                     | 2                        | 4                    | Stainless Steel |  |
| Screen   | 2                     | 12                       | 4                    |                 |  |

### **MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 12                       | 4                       | 0                       | 0                | 94                 | 5.25         |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

### **ADDITIONAL INFORMATION**

Obstructions: No

Authorization Official: \_\_\_\_\_

Obstruction Type: \_\_\_\_\_

Authorization Number: \_\_\_\_\_

Alternative Decomm. Method? No

Authorization Date: \_\_\_\_\_

Method Used \_\_\_\_\_

ATTACHMENTS: \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206  
Company: Netcong (Morris), NJ 07857

**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** BENJAMIN FARBER/ FARNOW, INC.

Company/Organization: B. Farber/Farnow, Inc.

Address: 77-83 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins

Address: 81 Jacobus Avenue

County: Hudson Municipality: Kearny Town Lot: 12 Block: 289

Easting (X): 599150 Northing (Y): 693761  
Coordinate System: NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 8, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_

**Local ID:** MW-12

Reason for Decommissioning: No longer in use

Finished Well Depth (ft.): 13

Was a New Well Drilled? N

Formation Type: Unconsolidated

New Well Permit Number: \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material        | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|-----------------|--|
| Borehole |                       |                          |                      |                 |  |
| Casing   | 0                     | 2                        | 4                    | Stainless Steel |  |
| Screen   | 2                     | 12                       | 4                    |                 |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 12                       | 4                       | 0                       | 0                | 94                 | 5.25         |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

**ADDITIONAL INFORMATION**

Obstructions: No

Authorization Official: \_\_\_\_\_

Obstruction Type: \_\_\_\_\_

Authorization Number: \_\_\_\_\_

Alternative Decomm. Method? No

Authorization Date: \_\_\_\_\_

Method Used \_\_\_\_\_

ATTACHMENTS: \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206  
Company: Netcong (Morris), NJ 07857



**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** FARNOW, INC.

Company/Organization: Farnow, Inc.

Address: 77 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins

Address: 89 Jacobus Avenue

County: Hudson Municipality: Kearny Town Lot: 13 Block: 289

Easting (X): 598696 Northing (Y): 693831  
Coordinate System: NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 2, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_

**Local ID:** MW-14R2

Reason for Decommissioning: No longer in use

Finished Well Depth (ft.): 12

Was a New Well Drilled? N

Formation Type: Unconsolidated

New Well Permit Number: \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material        | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|-----------------|--|
| Borehole |                       |                          |                      |                 |  |
| Casing   | 0                     | 2                        | 4                    | Stainless Steel |  |
| Screen   | 2                     | 12                       | 4                    |                 |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 12                       | 4                       | 0                       | 0                | 94                 | 5.25         |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

**ADDITIONAL INFORMATION**

Obstructions: No

Authorization Official: \_\_\_\_\_

Obstruction Type: \_\_\_\_\_

Authorization Number: \_\_\_\_\_

Alternative Decomm. Method? No

Authorization Date: \_\_\_\_\_

Method Used \_\_\_\_\_

ATTACHMENTS: \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206

Company: Netcong (Morris), NJ 07857

**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** BENJAMIN FARBER/ FARNOW, INC.

Company/Organization: B. Farber/Farnow, Inc.

Address: 77-83 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins

Address: 81 Jacobus Avenue

County: Hudson Municipality: Kearny Town Lot: 12 Block: 289

Easting (X): 598838 Northing (Y): 693784  
Coordinate System: NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 2, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_

**Local ID:** MW-19

Reason for Decommissioning: No longer in use

Finished Well Depth (ft.): 12

Was a New Well Drilled? N

Formation Type: Unconsolidated

New Well Permit Number: \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material        | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|-----------------|--|
| Borehole |                       |                          |                      |                 |  |
| Casing   | 0                     | 2                        | 4                    | Stainless Steel |  |
| Screen   | 2                     | 12                       | 4                    |                 |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 12                       | 4                       | 0                       | 0                | 94                 | 5.25         |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

**ADDITIONAL INFORMATION**

Obstructions: No

Authorization Official: \_\_\_\_\_

Obstruction Type: \_\_\_\_\_

Authorization Number: \_\_\_\_\_

Alternative Decomm. Method? No

Authorization Date: \_\_\_\_\_

Method Used \_\_\_\_\_

ATTACHMENTS: \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206  
Company: Netcong (Morris), NJ 07857

**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** FARNOW, INC.

Company/Organization: Farnow, Inc.

Address: 77 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins

Address: 89 Jacobus Avenue

County: Hudson Municipality: Kearny Town Lot: 13 Block: 289

Easting (X): 598679 Northing (Y): 694219  
Coordinate System: NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 2, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_

**Local ID:** MW-20-R

Reason for Decommissioning: No longer in use

Finished Well Depth (ft.): 10

Was a New Well Drilled? N

Formation Type: Unconsolidated

New Well Permit Number: \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material        | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|-----------------|--|
| Borehole |                       |                          |                      |                 |  |
| Casing   | 0                     | 1                        | 4                    | Stainless Steel |  |
| Screen   | 1                     | 9                        | 4                    |                 |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 9                        | 4                       | 0                       | 0                | 65                 | 3.5          |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

**ADDITIONAL INFORMATION**

Obstructions: No

Authorization Official: \_\_\_\_\_

Obstruction Type: \_\_\_\_\_

Authorization Number: \_\_\_\_\_

Alternative Decomm. Method? No

Authorization Date: \_\_\_\_\_

Method Used \_\_\_\_\_

ATTACHMENTS: \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206  
Company: Netcong (Morris), NJ 07857



**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** BENJAMIN FARBER/ FARNOW, INC.

Company/Organization: B. Farber/Farnow, Inc.

Address: 77-83 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins Superfund Site

Address: 81 Jacobus Avenue

County: Hudson Municipality: Kearny Town Lot: 12 Block: 289

Easting (X): 599055 Northing (Y): 693769  
Coordinate System: NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 8, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_

**Local ID:** PZ-1

Reason for Decommissioning: No longer in use

Finished Well Depth (ft.): \_\_\_\_\_

Was a New Well Drilled? N

Formation Type: Unconsolidated

New Well Permit Number: \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|----------|--|
| Borehole |                       |                          |                      |          |  |
| Casing   | 0                     | 3                        | 2                    | PVC      |  |
| Screen   | 3                     | 8                        | 2                    |          |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 8                        | 2                       | 0                       | 0                | 15                 | 1            |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

**ADDITIONAL INFORMATION**

Obstructions: No

Authorization Official: Michael Schumacher

Obstruction Type: \_\_\_\_\_

Authorization Number: A1611007

Alternative Decomm. Method? No

Authorization Date: November 7, 2016

Method Used \_\_\_\_\_

ATTACHMENTS: \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206  
Company: Netcong (Morris), NJ 07857

**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** BENJAMIN FARBER/ FARNOW, INC.

**Company/Organization:** B. Farber/Farnow, Inc.

**Address:** 77-83 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins Superfund Site

**Address:** 81 Jacobus Avenue

**County:** Hudson **Municipality:** Kearny Town **Lot:** 12 **Block:** 289

**Easting (X):** 598949 **Northing (Y):** 693850  
**Coordinate System:** NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 8, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_

**Local ID:** PZ-2

**Reason for Decommissioning:** No longer in use

**Finished Well Depth (ft.):** \_\_\_\_\_

**Was a New Well Drilled?** N

**Formation Type:** Unconsolidated

**New Well Permit Number:** \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|----------|--|
| Borehole |                       |                          |                      |          |  |
| Casing   | 0                     | 3                        | 2                    | PVC      |  |
| Screen   | 3                     | 8                        | 2                    |          |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 8                        | 2                       | 0                       | 0                | 15                 | 1            |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

**ADDITIONAL INFORMATION**

**Obstructions:** No

**Authorization Official:** Michael Schumacher

**Obstruction Type:** \_\_\_\_\_

**Authorization Number:** A1611008

**Alternative Decomm. Method?** No

**Authorization Date:** November 7, 2016

**Method Used** \_\_\_\_\_

**ATTACHMENTS:** \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206  
Company: Netcong (Morris), NJ 07857

**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** FARNOW, INC.

Company/Organization: Farnow, Inc.

Address: 77 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins Superfund Site

Address: 89 Jacobus Avenue

County: Hudson Municipality: Kearny Town Lot: 13 Block: 289

Easting (X): 598664 Northing (Y): 693856  
Coordinate System: NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 8, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_

**Local ID:** PZ-3

Reason for Decommissioning: No longer in use

Finished Well Depth (ft.): \_\_\_\_\_

Was a New Well Drilled? N

Formation Type: Unconsolidated

New Well Permit Number: \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|----------|--|
| Borehole |                       |                          |                      |          |  |
| Casing   | 0                     | 3                        | 2                    | PVC      |  |
| Screen   | 3                     | 8                        | 2                    |          |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 8                        | 2                       | 0                       | 0                | 15                 | 1            |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

**ADDITIONAL INFORMATION**

Obstructions: No

Authorization Official: Michael Schumacher

Obstruction Type: \_\_\_\_\_

Authorization Number: A1611009

Alternative Decomm. Method? No

Authorization Date: November 7, 2016

Method Used \_\_\_\_\_

ATTACHMENTS: \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206  
Company: Netcong (Morris), NJ 07857



**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** FARNOW, INC.

Company/Organization: Farnow, Inc.

Address: 77 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins

Address: 89 Jacobus Avenue

County: Hudson Municipality: Kearny Town Lot: 13 Block: 289

Easting (X): 598687 Northing (Y): 693898  
Coordinate System: NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 8, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_

**Local ID:** TW-1

Reason for Decommissioning: No longer in use

Finished Well Depth (ft.): \_\_\_\_\_

Was a New Well Drilled? N

Formation Type: Unconsolidated

New Well Permit Number: \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material | Wgt/Rate/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|----------|--|
| Borehole |                       |                          |                      |          |  |
| Casing   | 0                     | 3                        | 4                    | PVC      |  |
| Screen   | 3                     | 8                        | 4                    |          |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 8                        | 4                       | 0                       | 0                | 60                 | 3.5          |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

**ADDITIONAL INFORMATION**

Obstructions: No

Authorization Official: Michael Schumacher

Obstruction Type: \_\_\_\_\_

Authorization Number: A1611010

Alternative Decomm. Method? No

Authorization Date: November 7, 2016

Method Used \_\_\_\_\_

ATTACHMENTS: \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206  
Company: Netcong (Morris), NJ 07857

**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** FARNOW, INC.

Company/Organization: Farnow, Inc.

Address: 77 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins

Address: 89 Jacobus Avenue

County: Hudson Municipality: Kearny Town Lot: 13 Block: 289

Easting (X): 598707 Northing (Y): 693899  
Coordinate System: NJ State Plane (NAD83) - USFEET

**DATE WELL  
DECOMMISSIONED:** November 8, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_ **Local ID:** TW-2

Reason for Decommissioning: No longer in use

Finished Well Depth (ft.): \_\_\_\_\_

Was a New Well Drilled? N

Formation Type: Unconsolidated

New Well Permit Number: \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|----------|--|
| Borehole |                       |                          |                      |          |  |
| Casing   | 0                     | 3                        | 4                    | PVC      |  |
| Screen   | 3                     | 8                        | 4                    |          |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 8                        | 4                       | 0                       | 0                | 60                 | 3.5          |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

**ADDITIONAL INFORMATION**

Obstructions: No

Authorization Official: Michael Schumacher

Obstruction Type: \_\_\_\_\_

Authorization Number: A1611011

Alternative Decomm. Method? No

Authorization Date: November 7, 2016

Method Used \_\_\_\_\_

ATTACHMENTS: \_\_\_\_\_

David W Myerchin  
MASTER  
Sealing Driller: LICENSE # 726512

B & B DRILLING INC  
BOX 8 RT 206  
Company: Netcong (Morris), NJ 07857

**WELL DECOMMISSIONING REPORT**

**PROPERTY OWNER:** FARNOW, INC.

**Company/Organization:** Farnow, Inc.

**Address:** 77 Jacobus Ave Kearny, New Jersey 07032

**WELL LOCATION:** Syncon Resins

**Address:** 89 Jacobus Avenue

**County:** Hudson

**Municipality:** Kearny Town

**Lot:** 13

**Block:** 289

**Easting (X):** 598727 **Northing (Y):** 693900

**Coordinate System:** NJ State Plane (NAD83) - USFEET

**DATE WELL**

**DECOMMISSIONED:** November 8, 2016

**WELL USE:** MONITORING

**Other Use(s):** \_\_\_\_\_

**Local ID:** TW-3

**Reason for Decommissioning:** No longer in use

**Finished Well Depth (ft.):** \_\_\_\_\_

**Was a New Well Drilled?** N

**Formation Type:** Unconsolidated

**New Well Permit Number:** \_\_\_\_\_

**WELL DECOMMISSIONING INFORMATION**

|          | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Diameter<br>(inches) | Material | Wgt/Rating/Screen # Used<br>(lbs/ch no.) |
|----------|-----------------------|--------------------------|----------------------|----------|--|
| Borehole |                       |                          |                      |          |  |
| Casing   | 0                     | 3                        | 4                    | PVC      |  |
| Screen   | 3                     | 8                        | 4                    |          |  |

**MATERIALS USED**

|             | Depth to<br>Top (ft.) | Depth to<br>Bottom (ft.) | Outer<br>Diameter (in.) | Inner<br>Diameter (in.) | Material         |                    |              |
|-------------|-----------------------|--------------------------|-------------------------|-------------------------|------------------|--------------------|--------------|
|             |                       |                          |                         |                         | Bentonite (lbs.) | Neat Cement (lbs.) | Water (gal.) |
| Grout       | 0                     | 8                        | 4                       | 0                       | 0                | 60                 | 3.5          |
| Sand/Gravel |                       |                          |                         |                         |                  |                    |              |

**ADDITIONAL INFORMATION**

**Obstructions:** No

**Authorization Official:** Michael Schumacher

**Obstruction Type:** \_\_\_\_\_

**Authorization Number:** A1611012

**Alternative Decomm. Method?** No

**Authorization Date:** November 7, 2016

**Method Used** \_\_\_\_\_

**ATTACHMENTS:** \_\_\_\_\_

David W Myerchin  
MASTER

B & B DRILLING INC  
BOX 8 RT 206

Sealing Driller: LICENSE # 726512

Company: Netcong (Morris), NJ 07857